

Photo A: Kinder Morgan LS 16 pipeline with through-wall puncture.




Photo Courtesy of CalOSHA

Photo B: Kinder Morgan LS 16 with temporary clamp over puncture.



Photo Courtesy of CalOSHA

Photo C: Kinder Morgan LS 16 pipeline “offset” shown in the original location going around the oak tree stump.




Photo Courtesy of CalOSHA

Photo D: Kinder Morgan LS 16 pipeline “offset” section removed.



Photo Courtesy of CalOSHA

Photo E: Mountain Cascade excavator bucket with rock teeth.



Photo by CSFM Pipeline Safety - Tin Tran